

The Use of Post-Dredge Monitoring Data to Distinguish Between Impacts of Dredge Residuals and Ongoing Sources

Susan McGroddy, PhD

Windward Environmental LLC

Doug Hotchkiss

Port of Seattle



Harbor Island, Seattle, Washington





Phase 1 Dredging

- Dredging conducted over two dredging seasons in 2005 and 2006
- Removed 260,000 cy of sediment over ~20 ac
- New surface sediment sampled 48 hrs after completion of dredging
- Mercury and polychlorinated biphenyls (PCBs)
 primary contaminants of concern in surface sediment
- Dredge plan included contingency action to place sand cover materials in areas where surface sediment concentrations exceeded Washington State Sediment Management Standards (SMS)



Datasets


- Two sampling events prior to placement of sand cover material
 - 2005 post-dredge monitoring 68 locations sampled immediately following completion of dredging
 - 2005 pre-sand placement 37 locations re-occupied following additional 1 ft of dredging




Datasets

- Three sampling events following the placement of sand cover material
 - 2006 recontamination monitoring 30 locations sampled
 - 2007 recontamination monitoring 23 locations sampled
 - 2008 recontamination monitoring 9 locations sampled

Mercury Concentrations in Surface Sediment Immediately after Dredging (PDM)



- > 0.40 and ≤ 0.8
- > 0.8 and ≤ 1.2
- > 1.2 and ≤ 4.8
- > 4.8 and ≤ 11
- > 12 and ≤ 19
- > 19
- O Surface sediment sampling location
- Sand cover placement area






Mercury Concentrations in Surface Sediment after 1 ft Additional Dredging (PSP)

TERMINAL 18

0 0

O

О





TERMINAL 25

O

TERMINAL 30 > z 0 150 300 Feet 0 100 Meters


Mercury Concentrations in Surface Sediment 1 year after Placement of Sand Cover









Mercury Concentrations in Surface Sediment 2 yrs after Placement of Sand Cover












Mercury Concentrations Over Time



Total PCB Concentrations in Surface Sediment Immediately after Dredging

TERMINAL 18

2005 Post-Dredge Monitoring Total PCBs (µg/kg dw)

≤ 260

> 260 and ≤ 800


> 800 and ≤ 1,500


> 1,500 and ≤ 2,200

> 2,200

O Surface sediment sampling location

Sand cover placement area





Total PCB Concentrations in Surface Sediment after 1 ft Additional Dredging

TERMINAL 18

2005 Pre-Sand Placement

Total PCBs (µg/kg dw)

≤ 260

> 260 and ≤ 800


> 800 and ≤ 1,500

> 1,500 and ≤ 2,200

> 2,200


Surface sediment sampling location


- EW Pre-Sand Placement Monitoring
- O PostDredgeMonitoring-2005
- Sand cover placement area






Total PCB Concentrations in Surface Sediment 1 yr after Placement of Sand Cover









Total PCB Concentrations in Surface Sediment 2 yrs after Placement of Sand Cover

TERMINAL 18







Total PCB Concentrations in Surface Sediment 3 yrs after Placement of Sand Cover


TERMINAL 18

2008 Total PCBs (µg/kg dw)


- ≤ 260
- > 260 and ≤ 800
- > 800 and ≤ 1,500
- > 1,500 and ≤ 2,200
- > 2,200

Surface sediment sampling location

- □ Recontamination Monitoring 2008
- O Recontamination Monitoring 2007
- Sand cover placement area




TERMINAL 25







PCB Concentrations Over Time



1,4-Dichlorobenzene Concentrations in Surface Sediment Immediately after Dredging


TERMINAL 18






TERMINAL 25

1,4-Dichlorobenzene Concentrations in Surface Sediment 1 yr after Placement of Sand Cover



- > 19 and ≤ 63
- > 63 and ≤ 150
- > 150 and ≤ 290
- > 290
- O Surface sediment sampling location
- Sand cover placement area





1,4-Dichlorobenzene Concentrations in Surface Sediment 2 yrs after Placement of Sand Cover

TERMINAL 18

2007 1,4-Dichlorobenzene (µg/kg dw) ≤ 19

> 19 and ≤ 63


> 63 and ≤ 150

> 150 and ≤ 290

> 290

O Surface sediment sampling location

Sand cover placement area





1,4-Dichlorobenzene Concentrations in Surface Sediment 3 yrs after Placement of Sand Cover


TERMINAL 18

2008

- 1,4-Dichlorobenzene (µg/kg dw)
- ≤ 19
- > 19 and ≤ 63
- > 63 and ≤ 150
- > 150 and ≤ 290
- > 290

Surface sediment sampling location

- □ EW RCM 2008
- O Recontamination Monitoring 2007
- Sand cover placement area




TERMINAL 25





1,4-Dichlorobenzene Concentrations Over Time





Conclusions

- Inclusion of contingency action in dredge plan enabled effective response to address contaminants in post-dredge surface sediment
- Sand cover material placement reduced surface sediment concentrations of PCBs and mercury
- Recontamination monitoring data show
 - Minimal recontamination for mercury
 - Total PCB concentrations were elevated at a few locations
 - 1,4-dichlorobenzene concentrations increased over time



Acknowledgements

- Ravi Sanga, EPA project manager
- Craig Hanson, Windward Environmental LLC